Trat 1	TT'		IDD	T
L'Number	Hits	Search Text	DB	Time stamp
1	92	73/862.043.ccls.	USPAT	2003/04/25 13:41
2	243	73/826.ccls.	USPAT	2003/04/25 13:42
3	181	72/75.ccls.	USPAT	2003/04/25 13:42
4	140	72/379.6.ccls.	USPAT	2003/04/25 13:54
5	568	72/379.2.ccls.	USPAT	2003/04/25 13:55
8	74	(73/862.043.ccls. 73/826.ccls. 72/75.ccls. 72/379.6.ccls.	USPAT	2003/04/25 13:57
		72/379.2.ccls.) and (tensi\$4 near4 stress\$4)		
9	3329	(tensi\$4 near4 stress\$4 near4 (lower\$4 decreas\$4 minim\$4 reduc\$4	USPAT	2003/04/25 14:00
		diminish\$4))		
10	17	((tensi\$4 near4 stress\$4 near4 (lower\$4 decreas\$4 minim\$4	USPAT	2003/04/25 14:34
		reduc\$4 diminish\$4))) same ((compress\$4 pressur\$4 forc\$4		
		burnish\$4) near4 (chang\$4 vari\$4 divers\$4 differ\$4 manipulat\$4)		
		near4 (surface layer film body specimen metal\$4 plate))		
11	16	("1784866" "3494013" "3770595" "3820210" "4118846"	USPAT	2003/04/25 14:16
	1	"4132098" "4509351" "4565081" "4821388" "4947668"		
		"5099558" "5329684" "5522706" "5525429" "5666841"		
		"5826453").PN.		
15	805	29/90.01.ccls.	USPAT	2003/04/25 14:33
16	12	29/90.01.ccls. and ((compress\$4 pressur\$4 forc\$4 burnish\$4) near4	USPAT	2003/04/25 14:41
		(chang\$4 vari\$4 divers\$4 differ\$4 manipulat\$4) near4 (surface layer		
		film body specimen metal\$4 plate))		
17	28	burnish\$4 near4 densi\$4	USPAT	2003/04/25 14:42
	81	73/862.043.ccls.	USPAT	2003/04/25 13:41
	235	73/826\$3.ccls.	USPAT	2001/03/30 12:31
	79	73/826\$3.ccls. and method	USPAT	2001/04/03 16:14
-	235	73/826.ccls.	USPAT	2003/04/25 13:41
-	599	73/\$7.ccls. and method and tensile near3 stress	USPAT;	2001/04/03 16:16
-	399	73/\$7.ccis. and method and tensile hears sitess	EPO; JPO;	2001/04/03 10:10
			DERWENT;	
	1	72/07 -1	IBM_TDB	2001/04/03 16:29
-	14	73/\$7.ccls. and ((method and tensile near3 stress and	USPAT;	2001/04/03 10.29
1		pressure).clm.)	EPO; JPO;	
			DERWENT;	
			IBM_TDB	2001/04/03 16 10
-	1	73/\$7.ccls. and ((method and tensile near3 stress and	USPAT;	2001/04/03 16:19
		pressure).clm.) and cold near2 work\$2	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	2001/04/02 16 24
-	0	73/\$7.ccls. and method and measure and pressure and (tensile near3	USPAT;	2001/04/03 16:34
		stress) and (cold near2 work\$2) and burnish\$3	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	2001/04/02 16 21
-	14	73/\$7.ccls. and method and measure and pressure and (tensile	USPAT;	2001/04/03 16:21
		near3 stress) and cold near2 work\$2	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	2001/04/02 16 0=
(-	9	73/\$7.ccls. and method and measure and pressure and (tensile near3	USPAT;	2001/04/03 16:27
	1	(stress tension)) and (cold near2 work\$3) and (burnish\$3 rub\$3	ЕРО; ЛРО;	
		polish\$3 smooth\$3)	DERWENT,	
1		·	IBM_TDB	
-	47	73/\$7.ccls. and ((method and tensile near3 stress and pressure) and	USPAT;	2001/04/03 16:39
		(reduce lower short).clm.)	ЕРО; ЛРО;	
			DERWENT;	
	1		IBM_TDB	
-	0	(method and measure and pressure and (tensile near3 stress) and	USPAT;	2001/04/03 16:37
1		(cold near2 work\$2) and burnish\$3).clm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	1	method and measure and pressure and (tensile near3 stress) and	USPAT;	2001/04/03 16:34
		(cold near2 work\$2) and burnish\$3	EPO; JPO;	
			DERWENT;	
ı		1	IBM_TDB	1

Search History 4/25/03 2:50:32 PM Page 1



1	1
	J

-	15	(method and measure and pressure and (tensile near3 stress) and	USPAT;	2001/04/03 16:43
		(cold near2 work\$2) and (burnish\$3 rubbing rub smooth smoothing	ЕРО; ЛРО;	
		polish polishing))	DERWENT;	
			IBM_TDB	
-	1	(method and measure and (reduce lower decrease) and (tensile	USPAT;	2001/04/03 16:45
		near3 stress) and (cold near2 work\$2) and ((burnish\$3 rubbing rub	ЕРО; ЈРО;	
		smooth smoothing polish polishing) near3 (device apparatus	DERWENT;	
		machine)))	IBM_TDB	
-	2561	((elimina\$4 reduce\$ decreas\$4 lower\$4) and stress).ti.	USPAT;	2001/04/06 14:42
			ЕРО; ЛРО;	
	1		DERWENT;	
			IBM_TDB	
-	2070	((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress).ti.	USPAT;	2001/04/06 14:43
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	1415	((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress).clm.	USPAT;	2001/04/06 15:10
		·	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
	31	(((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress).clm.) and	USPAT:	2001/04/06 14:50
	1	cold near4 work\$3	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	9	((((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress).clm.) and	USPAT;	2001/04/06 14:51
		cold near4 work\$3).clm.	ЕРО; ЛРО;	
			DERWENT;	
	1		IBM_TDB	
-	308	((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress) and	USPAT;	2001/04/06 15:17
		(burnish\$4 polish\$4).clm.	EPO; JPO;	
			DERWENT;	(
	1		IBM_TDB	2001/04/06 15 12
-	1	((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress and	USPAT;	2001/04/06 15:13
		(burnish\$4 polish\$4)and cold).clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	2001/04/06 15 21
-	34	((elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress) and	USPAT;	2001/04/06 15:21
		(burnish\$4 polish\$ and compress\$4).clm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	2001/04/05 15 25
-	1	(cold and(elimina\$4 reduce\$ decreas\$4 lower\$4) near4 stress and	USPAT;	2001/04/06 15:25
		(burnish\$4 polish\$) and compress\$4).clm.	ЕРО; ЛРО;	
			DERWENT;	
			IBM TDB	